DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: <u>SF/ALA</u> Rte: <u>80</u> PM: <u>13.2/13.9</u>

File #: 69.12

DAILY PROJECT JOURNAL

Prime Contractor: American Bridge/Fluor Enterprises, a JV Report No: DPJ-000671 **Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Dated:** 08-Feb-2008

Location: Changxing Island, Shanghai, China

| Submittals(New / Total): CWR's: | | | WR's: / | HSR's: / | NCR's: / | |
|---------------------------------|----------------------------|-------------|----------|--|-----------------------------|--|
| Item | Title | | Detail | | | |
| 1 | 1 Major component movement | | OBG P | OBG Production: | | |
| | | | Machin | Machining, beveling and bending closed-ribs, | | |
| | | | No other | No other work was observed. | | |
| | | | Tower | Tower Production: | | |
| | | | No wor | No work observed. | | |
| | | | 77m To | ower Mock-up: | | |
| | | | No wor | k observed. | | |
| | | | 89m To | ower Mock-up: | | |
| | | | No wor | k observed. | | |
| | | | 114m T | Cower Mock-up: | | |
| | | | Drilling | g holes for tower splice. | | |
| Insp | pected By: | McClary,Dav | id | | Quality Assurance Inspector | |

Reviewed By: Lowry, Patrick **QA** Reviewer